Building Details Building Name: Darling Building No: NT 15 Date of Inspection: 16/06/2023 Inherent Risk Keys required: Roof Space Medium

Roof Access Details

- Roof cannot be accessed internally.
- If accessing roof externally a lock out/tag out procedure has been implemented for Fume Cupboards

<u>No access</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Space

• Right of Access Permit is only for visual inspection and a different permit is required before commencing any work in roof space.

There is internal access into the roof space from level 2 outside room 211d. Undo lock, remove chain from board restricting access to ladder, pull out ladder. As you enter manhole, light is on right hand side.

Entrance Walk way Walk way

Roof Details

Roof Material: Terracotta Tiles	No. of Roofs on Building: Three (3)
Pitch: 35° to 45°	Roof Height (m):

Warning	ning This process is uncontrolled when printed. The current version is available on the I&TS Website.		June 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University		June 2026	Page: 1 of 2	
Filepath	lepath S:\Services Resources\Infrastructure\Shared\HSW\01, Hazard Management\01 Roof Access\01 Risk Assessments\North Terrace\2023\Darling\NT 15 - Darling Roof Risk				

Infrastructure HSW Management Sub-System Roof Inspection Check