

I&TS HSW Management Sub-System

4-01F01 Roof Inspection Check

Building Details		
Building Name: Hickinbotham Building Building No: RW051	Date of Inspection: 10/04/2019	Inherent Risk
	Keys required: Plant Room	Medium

I&TS HSW Management Sub-System

4-01F01 Roof Inspection Check

Other Information

1. The method of access to rooftop shall depend on the specific job task being undertaken and risk assessment completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Method Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI);
2. Access and work on roof top when weather is clear, dry and when winds do not create added risk;
3. Footwear must comply with AS/NZS 2210 and appropriate to job task being undertaken;
4. Sun protection policy and procedure is in place when working outdoors;
- 5.