## I&TS HSW Management-System

## 4-01F01 Roof Inspection Check

Building Details		
Building NameleskeBuilding Building NoRW079	Date of Inspection: 10'04/2019	Inherent Risk
	Keys required: Plant Room	Medium
Roof Access Details		

There is external access to the roof from a fixed ladder in the plant area on the eastern entitle becitating to access the plant area. However, method of access shall depend on the specific job being undertaken via a risk assessment p

## I&TS HSW Management-Sybtem

## 4-01F01 Roof Inspection Check

		Do not carry out any tasks at an unguarded rounless a fall prevention device in impleimented restraint method.
Slip & trip hazard Walkingon roof	Rare x Minor Low	Walk and do not run. Wear protective footwea Uneven levels create trip hazards. Stop work if weather makes footing risky.
Environmental hazard		