

Roof Inspection Check

Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x Moderate Medium	Do not commence works in extreme weather conditions which will adversely affect workers. Wear a hat in open sun.
Working alone	Slight x Major High	A system to ensure lone worker's welfare, needs to be in place.
Airbourne hazardous chemicals (Venting or Flumes)	Rare x Moderate Low	