

**SAFETY INFORMATION**

NAME OF THE TASK/ACTIVITY	ZEISS AXIO SCAN.Z1 SLIDE SCANNER	DATE: 12/02/2020
LOCATION	ADELAIDE MICROSCOPY, AHMS LEVEL 6	Insert photo (Optional)
Residual risk rating on the RA	Low      Medium      High      Very High	
Hazards identified on the RA	Contact with electricity or potential for electric shock	

**This Safety information should be provided to new users for them to read before undertaking and tasks/activities on the microscope.**

**Pre-operational checks**

YOU MUST NOT USE THIS MACHINE UNTIL YOU HAVE HAD APPROPRIATE TRAINING BY TRAINED ADELAIDE MICROSCOPY STAFF. Unauthorised use may result in damage to the instrument.

**Operational checks/steps to complete the activity from start to finish (including transport and waste disposal where relevant)**

The Zeiss Axio Scan.Z1 slide scanner is an optical microscope which automatically images larger numbers of slides. Axio Scan.Z1 Automated Slide Scanner for brightfield, POL and fast fluorescence imaging Feeder with 100 slide capacity, 4 slides per mounting frame (76x26mm).

The only user operable parts on the Axio slidescanner are the specimen holder, and the computer system (mouse and keyboard).

There is no risk involved in the operation of any of these parts. However, there is potential for electric shock if a user were to remove panels from the back of the microscope, also potentially resulting in damage to the instrument.

**All new users must have a practical demonstration of the operation of the machine from a member of Adelaide Microscopy staff.**

**Users should operate the instrument in accordance with the manufacturer supplied operating instructions to avoid damage to the instrument.**

**The user operable parts are all accessible from the operator’s console; users of the instrument should not attempt to remove any fixture or panel from the microscope.**

**Users should not access the rear of the instrument.**

The safe handling of general laboratory items is detailed in the Adelaide Microscopy laboratory general safety procedures.

Low stocks of consumable items (gloves, paper towel etc.) should be reported to a member of AM staff.

**On completion of work – steps to make safe (including clean up, any waste disposal & service/maintenance requirements)**

Remove all samples from the instrument and the laboratory after imaging.