

**Building Details**

Building Name: Lower Napier Building No: NT 33	Date of Inspection: 21/09/2023	Risk
	Keys Required: Roof Access	Medium

**Roof Access Details**

Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.

If using a harness attached to an anchor point/static line all workers must have current Working at Heights training and anchor points/static lines must have been certified in the last 12 months.

There is internal access from Level 2 of the Napier Building. Entry is from corridor at the western end. Access to the roof is through the locked glass doors adjacent to fire safety door on level 2.

Access door      Courtyard      Eastern plant      Western plant

No access to roof unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS

Infrastructure HSW Management Sub-System

Roof Inspection Check