

LOCATION	ADELAIDE MICROSCOPY, ISOTOPE LABORATORY, HELEN MAYO NORTH, NB45				Insert photo (Optional)			
<b>RISK ASSESSMENT (RA) NAME</b>	Agilent 8900 Solution ICPMS and 7900 ICPMS							
Residual risk rating on the RA	Low	Medium	High	Very High				
Hazards identified on the RA	Contact with electricity or potential for electric shock Exposure to chemicals, fumes and gases Exposure to UV light							
<b>PERSONAL PROTECTIVE EQUIPMENT</b>								
	Eye protection:	Safety glasses	Eye shields	Safety goggles				
	Other:							
	Hand protection:	Rubber	Cut resistant	Leather	Vinyl	Neoprene	Nitrile	Barrier creams
	Other:							
	Enclosed footwear:	Footwear that is resistant to spills of hazardous substances			Boots with steel caps			
	Other:							
	Protective clothing:	Lab coat	Gown	Long sleeves	Long pants	High visibility	Helmet	Sun protection
	Other:							

Hazards

HSW Handbook	Hazard Management	Effective Date:	17 December 2019	Version 3.0
Authorised by	Chief Operating Officer (University Operations)	Review Date:	17 December 2022	Page 1 of 2
Warning	This process is uncontrolled when printed. The current version of this document is available on the HSW Website.			

